

(No. 9)

LEE JOHNSON

(No. 10)

Bulldozer bringing in earth from left downstream bank. Top of riser forms are seen in left center.

View taken from approximately same spot as picture No. 1.



Looking North. One anti-seep collar yet to be covered. Note lateral to N.W. has been covered.

Fill was supposed to have been placed in equal layers horizontally over the entire fill, keeping the top surface level.





