

(No. 3)

LEE JOHNSON

Looking South-southwest. Observer is facing upstream. North-south property line fence is visible on hill to left. The trees in foreground are growing down in the lateral. This lateral enters from the right.



(No. 4)

Picture shows installation of pipe and anti-seep collars. 150 feet of 21" corrugated metal pipe were installed. This pipe was asbestos bonded and asphalt coated.





