

CASS COUNTY ROAD STRUCTURE

Right view shows observer looking down the centerline of the proposed earthfill. Note remnants of the bridge and pilings.

Left view shows the concrete work complete except for the riser, the base of which has been poured (see the reinforcing steel protruding upward)



Location?
Watershed?



