

NOV

59

(2)



Photo taken from same
location as photo showing
structure & completed diversion
This photo was taken before
start of any construction
work

A. Jay farm

Photo Peterson SCS

NOV 59



On the left Henry Burgher
contractor talking to Art Jay.
Shows laying of pipe &
fitting of anti-seep collars

A. Jay farm

1513

Photo by Peterson SES

NOV 59



Taken from NW corner of fill
after completion of the structure
showing fill & diversion
leading to structure

A. Jay farm

(12)

2 X 2

Photo Peterson scs

59

NOV



Photo taken from N.W.
corner of fill, showing fill
& diversion after completion
of structure

A. Jay Farm

Photo Peterson 505

59

NOV



Art Jay - Ponding area of
structure taken from center
of fill before completion of
structure

Photo by Wyle C Peterson SES

1

59

NOV



Art Jay standing in gully
before work commenced on
retention structure

A. Jay farm

15A

Photo by L.C.P.

SES

59

NOV



Art Jay working on
completing the pipe laying
in his structure

Photo Peterson, JCS


59

NOV



Ward Daniels & Art Jay
fitting the anti-scoop
collar on the Art Jay
structure

2x2



Return Service
to Cons. Sec.
Box 355
Centerville, Mo.

Photo by Peterson

505



Spring 1960 Arthur Jorg
structure

Cover Pix

APPANOOSE CO. SOIL
CONSERVATION DISTRICT

Centerville, Iowa

sep



Spring 1960 Arthur Jay structure
and diversion



16

APPANOOSE CO. SOIL
CONSERVATION DISTRICT
Centerville, Iowa

SEP



25th

Spring 1960 Arthur Jay structure
and diversion completed

150

APP MOOSE CO. SOIL
CONSERVATION DISTRICT
Centerville, Iowa

139

SCP



Fall 61 T. Brown. A. Engc.
checking pipe installation on
A. Jay structure



Fall 61 - An Jay & T. Brown
Area Engrs. during Const. of
Jay's 2nd structure on his
farm.




Fall 61 - Art Jay structure
during construction

~~11/1~~

2x2x

#1313



1 3/4 x 2 3/4

~~11~~

Fall 61- H. Burghes Contractor
M. Sinclair Eng. Tech. on road
during pipe install on A. Jay
structure

