

Yeager Site

Looking east (downstream)

@ erosion causing snag
and Flint River channel
(eroded bank to right of
picture, obscured by vegetation.)

Flint Creek streambank on Robert Yeager
property before any work is completed.