

DATE: 6/7/73

MHC-420-15

SUBJECT

EROSION-Gully

PHOTOGRAPHER

Erwin W. Cole

LOCATION

Lincoln Twp., Iowa

SOD OR WATERSHED

Plymouth County, Iowa

STOCK OWNER

Clarence Voss, Kingsley, Iowa

THIS PICTURE SHOWS: A large gully which is threatening a feedlot and a county road bridge. This shows the type of problem that can be solved with group cooperation.

PLEASE CREDIT: USDA-SOD CONSERVATION SERVICE

203-CART 204-Box 7-09