

MAX SANDERS FARM ---- Cass

View shows the crew surveying the borrow pit after construction in order to determine borrow yardage. P.S. We got an unexpected rain! Completed fill is in background. Water lacks $3\frac{1}{2}$ feet from being up to the top of the riser.

