




Julied
Ww on Bill Bruck's
fm. (Richland Twp)

1 of 4

Bill Bruck

2 of 4



Wm Bruck WW + structure
after 4-5" Rain 7/18-19/63
W.W. sdg hadn't got started.
Some minor cutting in W.W.
but structure stabilized outlet.

Bill Bruck

3 of 4

Bill Bruck

1963

4 of 4