

LEE JOHNSON (No. 1)

This set of pictures show various stages of construction of a gully control structure on the east property line of the Lee Johnson farm $1\frac{1}{2}$ miles south of the town of Lewis, Iowa

View looking southeast (downstream).

Observer is standing 10 feet this side of property line on a point of land between

lateral and main.
Lateral joins the
main gully behind
the observer.



(No. 2)

Looking East (downstream). Gully is approximately 23 feet deep. The observer is again standing on the point of land between lateral and main.





