

C. W. HANCOCK FARM -- Cass

Views show centerline of pipe spillway before and during construction. About eight feet of excavation was necessary at the upper end by the riser.





