



Mo-640 - C. L. Logsdon farm, Tarkio, Mo. 4/22/37. Showing sheet erosion on field drilled up and down on 8 percent slope. Silt deposit at base of slope more than 12 inches deep along fence line. This picture was taken two days after heavy rain amounting to $4\frac{1}{4}$ inches in 2 hours.