

10-536-1



SUBJECT: Land Treatment NO. Io-536-1
LOCATION: 3 miles northwest of Moulton, Iowa.

SCD OR WSHD: Appanoose, MOULTON WATERSHED
~~PROJECT~~ OWNER: M. Anderson Farm


THIS PICTURE SHOWS: Looking northwest at 80 acres of land treatment which contributes to B-5 structure to the south. Treatments are grade stabilizing structure with diversion protection at the northwest end, terracing and contouring of cropland, grassed waterway construction, and land clearing.

PHOTOGRAPHER: Erwin W. Cole

DATE: 4/10/64

PLEASE CREDIT: USDA - SOIL CONSERVATION SERVICE

10-536-2



SUBJECT: Land Treatment NO. 10-536-2
LOCATION: 3 miles northwest of Moulton, Iowa.

SCD OR WSHD: Appanoose, MOULTON WATERSHED
PROPOSED OWNER: M. Anderson farm

THIS PICTURE SHOWS: Looking west at 80 acres of land treatment north of structure B-5. Treatment shown is not cost shared with P.L. 566 funds. Shown are terraced cropland with contouring, grassed waterways, grade stabilizing structure and contributing diversion, and land clearing.

PHOTOGRAPHER: Erwin W. Cole
PLEASE CREDIT: USDA - SOIL CONSERVATION SERVICE

DATE: 4/10/64

10-536-4



SUBJECT: Structure B-9 NO. 10-536-4
LOCATION: 3 miles west and south of Moulton, Iowa.

SCD OR WSHD: Appanoose, MOULTON WATERSHED
PEOPLE:

THIS PICTURE SHOWS: B-9 structure is located on farm-to-market road and contracted by Appanoose County Board of Supervisors under P.L. 566. The timbered area belongs to J. Frank Daniels and to the left center is J. R. Lindley farm. Land treatment includes strip cropping and or terracing, contouring, waterway construction, ponds, and pasture seedings of birdsfoot trefoil.

After picture of B-9; "Before" picture is 10-490-2

PHOTOGRAPHER: Erwin W. Cole
PLEASE CREDIT: USDA - SOIL CONSERVATION SERVICE

DATE: 4/10/64

10-536-7



Structure Site

SUBJECT: B-100 - Before NO. 10-536-7
LOCATION: 4 miles west of Moulton, Iowa.

SCD OR WSHD: Appanoose, MOULTON WATERSHED

~~PREVIOUS~~ OWNERS: D. Anderson, Sigal Mikals, Lattie
Daniels, Joe Daniels, W. H. Daniels, A. Daniels,

THIS PICTURE SHOWS:

Singley Estate

B-100 channel construction location on the upper E-W
section, looking east. The channel will extend 1/2
mile from the farm road in the foreground, straight
east, and end at a concrete weir-notch grade stabili-
zation structure. The channel will turn south at
the lower right-hand corner and follow the old ditch
to the Chariton River.

FILE COPY

Do Not Remove

PHOTOGRAPHER: Erwin W. Cole

DATE: 4/10/64

PLEASE CREDIT: USDA - SOIL CONSERVATION SERVICE

10-536-9



Runoff Retarding; Land Treatment
SUBJECT: Structure NO. Io-53649
LOCATION: 3½ miles southwest of Moulton, Iowa.

SCD OR WSHD: Appanoose, MOULTON WATERSHED
PEOPLE:

THIS PICTURE SHOWS: Retarding structure with contributing diversion bringing additional acreage. Other land treatments include waterway construction below the dam, farm pond in center, and pasture improvement. The fence line along the left border has earth fills with drainage - no water gaps. Grade stabilization structure will be built in the ditch at the left center on the fence line. See Io-536-12 and Io-537-1. This is the Stuart Daniels farm and Art Jay farm in the background.

PHOTOGRAPHER:

DATE:

4-10-64

PLEASE CREDIT: USDA - SOIL CONSERVATION SERVICE

10-536-12



Runoff Retarding

SUBJECT: Structure NO. Io-536-12
LOCATION: 3½ miles southwest of Moulton, Iowa.

SCD or WSHD: Appanoose, MOULTON WATERSHED
~~PROPERTY~~ OWNER: Arthur Jay

THIS PICTURE SHOWS: Land treatment runoff reduction or
retarding structure and constructed waterway below.
At left center a contributing diversion brings in
additional acreage behind the dam. Terraced ridge tops
are at the head of the subwatershed. Field strip
cropping is at the lower right outside of the photo.
Terracing and contouring are in the lower right. See
photos Io-536-9 and Io-537-1.

PHOTOGRAPHER: Erwin W. Cole

DATE: 4/10/64

PLEASE CREDIT: USDA - SOIL CONSERVATION SERVICE