





DATE May 1965 NO. 50-L-96-2  
SUBJECT : Tile Outlet Damage  
PHOTOGRAPHER : Cal Cox  
LOCATION : 1 mile west and 3 miles south of  
Gilmore City, Iowa.  
SOIL OR WATERWAYS : Pocahontas SCD-81  
FIGURE :

THE PICTURE SHOWS Tile line break through on bench-  
type terraces on the Leahy farm. The damage was  
caused by heavy spring thaw.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

SCS-124