

10-2-4/5-5



DATE: 11/5/70

NO. IO-L-415-5

SUBJECT

RC & D Project Proposal

PHOTOGRAPHER

Bill Stark

LOCATION

Indian Hills Com. College-Centerville
Campus

SCD OR WATERSHED: Appanoose County Ia, Centerville, Ia

PEOPLE

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC & D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Erosion control and netting will be used where most practical. This photo shows general view from the N.E. of interior sidewalk, unprotected slopes and building elevation. Farm tenements in left foreground. See view #6 for close-up.

PLEASE CREDIT: USDA—SOIL CONSERVATION SERVICE

503-104

10-4-415-6



DATE: 11/5/70

NO. IO-L-415-6

SUBJECT

RC & D Project Proposal

PHOTOGRAPHER

Bill Stark

LOCATION

Indian Hills Com. College-Centerville
Campus

SCD OR WATERSHED: Appanoose County Ia, Centerville, Ia

PEOPLE

THIS PICTURE SHOWS: one of twelve views within the build-
complex of the Centerville campus showing uncontrolled
sion and sedimentation. RC & D project proposal includes
treatments, underground drains for surface and building
off, sodding steepest slopes and seeding remaining areas.
ch and netting will be used where most practical. This
to shows close-up of sidewalk in center of view #5. Silt
ers this walk after runoff. Erosion is undermining the
er side. See view #7 for close-up of slope in upper left
ner.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

SCS-184

FILE COPY

Do Not Remove

10-1-415-16



DATE: 11/5/70

NO. IO-L-415-16

SUBJECT

: RC&D Project Proposal

PHOTOGRAPHER

: Bill Stark

LOCATION

: Indian Hills Com. College-

Centerville Campus

SCD OR WATERSHED

: Appanoose County Ia, Centerville, Ia

PEOPLE

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC&D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and netting will be used where practical. This photo shows campus parking area north of building complex. Cropland in background will be converted to recreation area.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

SCS-CART-164 Rev. 7-69

20-L-415-7



DATE: 11/5/70

SUBJECT

PHOTOGRAPHER

LOCATION

NO. 10-L-415-8
RC & D Project Proposal
Bill Stark
Indian Hills Com. College-
Centerville Campus
SCD OR WATERSHED : Appanose County Ia., Centerville,
PEOPLE : Ia.

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC & D project proposal includes treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and netting will be used where most practical. This picture shows result of concentration of runoff on one-to-one slope. Foundation of this building endangered if not controlled soon. See view #9 for general view of this area.

PLEASE CREDIT: USDA—SOIL CONSERVATION SERVICE

KODAK SAFETY FILM

10-4-415-9



DATE: 11/5/70

NO. IO-L-415-9

SUBJECT

RC & D Project Proposal

PHOTOGRAPHER

Bill Stark

LOCATION

Indian Hills Com. College-

Centerville Campus

SOC OR WATERSHED: Appanoose County Ia., Centerville, Ia

PEOPLE

THIS PICTURE SHOWS one of twelve views within the building complex of Centerville campus showing uncontrolled erosion and sedimentation. RC & D project proposal includes soil treatments, underground drains for surface and building runoff, grading steepest slopes and seeding remaining areas. Mulch netting will be used where most practical. This photo shows general view from S.E. of same slope (left) shown in photo #8. Note difference in building elevations. Building on left is cross shaped and its roof drainage is divided equally to eight downspouts. See photo #10 for view from other building elevation.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

10-L-415-10



DATE: 11/5/70

NO. 10-L-415-10

SUBJECT

: RC & D Project Proposal

PHOTOGRAPHER

: Bill Stark

LOCATION

: Indian Hills Com. College-

Centerville Campus

SCD OR WATERSHED

: Appanoose County Ia., Centerville,

PEOPLE

Ia.

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville Campus showing uncontrolled erosion and sedimentation. RC & D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and seeding will be used where most practical. This photo shows general view from S.E. through campus building complex. Each building is located on different elevation. Poor draining onto sidewalks can produce ice in wintertime creating safety hazard.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

SCS-154

10-L-415-11



DATE: 11/5/70

NO. Io-I-415-11

SUBJECT

: RC&D Project Proposal

PHOTOGRAPHER

: Bill Stark

LOCATION

: Indian Hills com. College--

Centerville Campus

SCD OR WATERSHED : Appanoose County Ia., Centerville,
PEOPLE :

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC&D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and netting will be used where most practical. This picture shows general view down hill from center of building complex toward camera station in photo #5. Considerable runoff water is concentrated here and then it flows between the two buildings in right background.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

SCS-CART-164 Rev. 7-69

10-1-415-12



DATE: 11/5/70

NO. IO-L-415-12

SUBJECT

: RC&D Project Proposal

PHOTOGRAPHER

: Bill Stark

LOCATION

: Indian Hills Com. College-

Centerville Campus

SCD OR WATERSHED : Appanoose County Ia., Centerville, Ia

PEOPLE

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC&D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and netting will be used where most practical. This photo shows east edge of campus building complex bordering First Street. Two alternatives to sodding this slope are: 1. Soil treatment and establish emerald crown vetch with help from mulch and netting or, 2. Construct retaining wall.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

SCS-CART-164 Rev. 7-69

10-4-415-15



DATE: 11/5/70

NO. IO-I-415-15

SUBJECT : RC&D Project Proposal

PHOTOGRAPHER : Bill Stark

LOCATION : Indian Hills Com. College-

Centerville Campus

SCD OR WATERSHED : Appanoose County Ia., Centerville, Ia

PEOPLE :

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC&D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and netting will be used where most practical. This photo shows erosion and silt fans in central area of building shown in photo #14. Soil eroding from the slope between the two buildings is filling drainage way at lower level

PLEASE CREDIT: USDA-SOIL CONSERVATION SERVICE

SCS-CART-164 Rev. 7-69

10-4-415-14



DATE: 11/5/70

NO. IO-L-415-14

SUBJECT

: RC&D Project Proposal

PHOTOGRAPHER

: Bill Stark

LOCATION

: Indian Hills Com. College-Centerville

Campus

SCD OR WATERSHED : Appanoose County Ia., Centerville, I

PEOPLE :

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC&D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and netting will be used where most practical. This photo shows still another critical erosion area adjacent to same building shown in photo #13. This slope is shown between two buildings in photo #15.

PLEASE CREDIT: USDA-SOIL CONSERVATION SERVICE

SCS-CART-164 Rev. 7-69

10-L-415-12



DATE: 11/5/70

NO. IO-L-415-12

SUBJECT

RC&D Project Proposal

PHOTOGRAPHER

Bill Stark

LOCATION

Indian Hills Com. College-
Centerville Campus

SCD OR WATERSHED : Appanoose County Ia., Centerville, Ia.
PEOPLE

THIS PICTURE SHOWS: one of twelve views within the building complex of the Centerville campus showing uncontrolled erosion and sedimentation. RC&D project proposal includes soil treatments, underground drains for surface and building runoff, sodding steepest slopes and seeding remaining areas. Mulch and netting will be used where most practical. This photo shows east edge of campus building complex bordering First Street. Two alternatives to sodding this slope are: 1. Soil treatment and establish emerald crown vetch with help from mulch and netting or, 2. Construct retaining wall.

PLEASE CREDIT: USDA--SOIL CONSERVATION SERVICE

SCS-CART-154 Rev. 7-69

FILE COPY

Do Not Remove